

Mitutoyo

直角度測定器 スコヤマスタ

SL-150

SL-250

SL-450

ユーザーズマニュアル – 取扱説明書 –

ご使用前に本書をよくお読みのうえ、
正しくお使いください。お読みになった後は、
いつでも見られる所に必ず保管してください。

No. 99MBF600B
2022年2月1日 発行 (1)



■ 本書の対象商品名および型番

商品名	型番
直角度測定器 スコヤマスタ	SL-150
	SL-250
	SL-450

■ 本書に関するお願いとご注意

- ・本書に記載の使用法に依らない使用により損害が発生した場合には、弊社は一切その責任を負いかねます。
- ・本商品を貸与または譲渡するときは、本書を本商品に添付してください。
- ・本書を紛失または損傷されたときは、すみやかにお求めの販売店、または弊社営業・サービスの窓口へ連絡してください。
- ・本商品の操作の前に本書をよく読んでください。特に、冒頭の「安全上のご注意」「取り扱い上のご注意」の内容を十分に理解してから本商品をお使いください。
- ・本書の内容は 2022 年 2 月現在の情報に基づいています。
- ・本書の内容の一部または全部を転載・複製することは固くお断りいたします。
- ・本書に掲載している画面図は、説明の都合上、強調や簡略化、または一部を省略していることがあります。また、機能理解と操作に支障を与えない範囲内で、実際の画面表示と異なることがあります。
- ・本文中の会社名、団体名、商品名等は、各社、各団体の商標、または登録商標です。

©2022 Mitutoyo Corporation. All rights reserved.

本書で使用されているマークや文字

■ 潜在的な危険性に対する注意喚起を示すマークや文字



注意

取り扱いを誤った場合、「軽傷を負う可能性が想定される」内容を示します。

注記

取り扱いを誤った場合、「物的損害の発生が想定される」内容を示します。



手や腕を挟まないよう注意

手を挟む危険性があることを示します。

■ 行為の禁止および行為の強制を示すマーク



行為の禁止の具体的な内容を示します。



行為の強制の具体的な内容を示します。

■ 参考情報や参照先を示すマークや文字

Tips

本文で説明している操作方法や手順に関連する詳細情報および参考情報を示します。



本書または外部の取扱説明書に、参照するべき情報がある場合は、参照先を示します。

例：○○の詳細は、□□「1 概要」の「1.1 各部の名称」(5 ページ)

安全上のご注意

ご使用の前に、この「安全上のご注意」をよくお読みのうえ、正しくお使いください。

ここに示した注意事項は、お使いになる人や、他の人への危害、財産への損害を未然に防ぐための内容を記載していますので、必ずお守りください。

注意

本商品やオプションを移動する際、取り扱いを誤るとけがをするリスクがあります。

 本商品は重量物のため（SL-450の場合、24 kg）、一人で持ち上げたり、持ち上げて移動したりしないでください。運搬、設置時には安全靴の使用を推奨します。

 本商品が落ちたり倒れたりすると、けがの原因になることがあります。慎重に取り扱いください。



本商品を定盤やライザブロック（オプション）に設置する際、本商品との間に手を挟んだけがをしないように注意してください。

取り扱い上のご注意

■ 本商品の用途や取り扱いについて

- 本商品は直角度測定器です。
本商品を直角度測定以外の目的に使用しないでください。
- 本商品は精密機器です。
取り扱いには十分注意してください。開梱、設置、ご使用時、保管時に各部に衝撃を加えたり、無理な力をかけたりしないように十分注意してください。
- 本商品に衝撃などを与えた場合は、精度を損なう恐れがあります。
- 縦姿勢専用のため、横姿勢では使用しないでください。

■ 使用環境

次の場所で本商品をご使用ください。

- 定盤上（必須）
本商品は、精密定盤の上に設置して使用するよう設計されています。精密定盤を用意してください。
- 塵や埃の少ない場所
- 振動の少ない場所
- 推奨温度として 20 °C 程度の環境下で温度変化が少ない場所
- 湿度の低い場所（70% 以下）

Tips

本商品を使用する場合は必ず十分な温度慣らしをしてください。

次のような場所での使用は避けてください。

- 切削油や水などの影響を直接受ける場所
- 直接日光、熱風、冷風の当たる場所
- 空調の風が直接当たる場所

■ 運搬・移動

本商品を輸送する場合は、衝撃がかからないように輸送用固定ねじを締め（「1.2 各部の名称と機能」（2 ページ））、バランサー固定ねじ（パーツ No. 390823）を取り付け（「2.3 輸送用固定具の取り外し・取り付け」（5 ページ））、出荷時の箱で梱包してください（「2.1 梱包仕様」（3 ページ））。

■ 分解・改造

本商品は組み立ての際、精密に調整されています。本書に記載されている内容以外の調整および分解・改造は精度に影響を与えるため、絶対に行わないでください。

■ お手入れについて

ご使用後は、レンズペーパーまたは繊維の出ない布などで支持脚（3箇所）と主柱の汚れを拭き取り、液体防錆油を薄く塗布してください（防錆処理）。洗剤、シンナーやベンジンなどの有機溶剤は使用しないでください。

詳細は、「4 保守」（19 ページ）

輸出および非居住者への技術提供にあたってのご注意

本商品は、「外国為替および外国貿易法の輸出貿易管理令別表第1もしくは外国為替令別表に定める16の項」によるキャッチオール規制貨物・キャッチオール規制技術（プログラムを含む）です。

本商品の輸出および日本国非居住者への技術提供にあたっては、経済産業省の許可が必要になる場合があります。

また、本商品に機能を追加するためにオプションの追加や改造を行った場合、「外国為替および外国貿易法の輸出貿易管理令別表第1もしくは外国為替令別表に定める1から15の項」によるリスト規制貨物、リスト規制技術（プログラムを含む）に該当となることがあります。その場合の本商品の輸出および日本国非居住者への技術提供にあたっては、経済産業省の許可が必要になります。事前に弊社にご相談ください。

EU（欧州）諸国への輸出に関するご注意

EU 加盟国へ本商品を輸出される際は、英文の取扱説明書・EU適合宣言書（場合によっては輸出国公用語の取扱説明書・EU適合宣言書）が必要となる場合があります。詳細につきましては弊社にご相談ください。

日本国内で本商品を廃棄する際のご注意

- ・事業者として廃棄する場合は、廃棄物の処理および清掃に関する法律（廃棄物処理法）等の関連法令に従い、適正な廃棄処理をしてください。
- ・個人として廃棄する場合は、各自治体の廃棄ルールに従ってください。

保証

本商品は、厳重な品質管理のもとで製造されていますが、お客様の正常な使用状態において、万一お買い上げの日から1年以内に故障した場合には、無償で修理させていただきます。お求めの販売店、または弊社営業・サービスの窓口へご連絡ください。

次のような場合には、保証期間内でも有償修理となります。

- 使用による通常の損耗によって生じた故障および損傷
- メンテナンス上、修理上または取り扱い上の誤りおよび不当な改造による故障および損傷
- お買い上げ後の移動、落下あるいは輸送による故障および損傷
- 火災、塩害、ガス害、異常電圧、雷サージおよび天災地変などによる故障および損傷
- ミツトヨによって指定されまたは許可されているハードウェアまたはソフトウェア以外のハードウェアまたはソフトウェアと組み合わせて使用したことによる故障および損傷
- 高度に危険な活動に使用したことによる故障および損傷

本保証は日本国内において適切に設置され、本書に記載される指示に従って操作されている場合にのみ有効です。

本保証に規定される場合を除き、適用される法によって許される最大の範囲で、あらゆる性質の、すべての明示的・黙示的な条件、表明および保証（商品性に関する保証、特定の目的への適合性の保証、非侵害の保証または取引過程、使用または取引実務から生じる保証を含みますが、これらに限定されません）は、排除されます。

お客様は、お客様が意図された結果を実現するために本商品を選択したことによって生ずるすべての結果についての全責任を引き受けるものとします。

免責

ミツトヨ、その関連会社およびそのサプライヤーは、いかなる場合においても、収益の損失、利益の損失、もしくはデータの損失、または本商品の使用もしくは使用不能によって生じた特別損害、直接損害、間接損害、派生的損害、付随的損害、または懲罰的損害について、原因および責任理論の如何にかかわらず、たとえミツトヨ、その関連会社またはそのサプライヤーが当該損害の可能性について通知を受けていた場合であっても、責任を負いません。

前記にもかかわらず、ミツトヨが、お客様による本商品の使用によって生じた損害または損失に対して責任があると判断された場合でも、いかなる場合においても、ミツトヨ、その関連会社およびそのサプライヤーのお客様に対する責任は、契約に基づくと、(過失を含む) 不法行為とを問わず、本商品に対してお客様が支払った金額を超えないものとします。

国、州、または管轄地によっては、派生的損害または付隨的損害に対する責任の排除または制限を認めていない場合があります。そのような国、州、または管轄地におけるミツトヨの責任は、法に認められる最大の範囲内で排除または制限されるものとします。

本書について

■ 本書の位置付け、ドキュメントマップ

本書のほかに、検出器関連のユーザーズマニュアルがあります。

スコヤマスタ
ユーザーズマニュアル
(本書)

開梱・設置マニュアル

● 検出器関連（標準付属）

テストインジケータ
ユーザーズマニュアル

● 検出器関連（オプション）

電気マイクロメータ
アナログミューチェック
ユーザーズマニュアル

ミューチェック用
レバーヘッドプローブ
ユーザーズマニュアル

■ 本書の対象読者と目的

● 対象読者

測定器の校正の基礎知識がある方を対象にしています。

図面を読んで指示を理解できることを前提とします。

● 目的

本書は、スコヤマスタの概要、各部の機能、使用方法、保守内容などをご理解いただくことを目的としています。

■ 本書の読み方

2 セットアップ

2.2 スコヤマスタの設置

次の手順で本商品を定盤の上に設置してください。

□ 溶剤などを浸したレンズペーパーまたは繊維の出ない布などで、定盤面と本商品の支持脚（3箇所）の汚れや油を拭き取る

Tips

- ゴミ、汚れ、油などの付着は測定誤差の要因となります。
- 推奨する溶剤：アルコール

□ 本商品を定盤の上に設置する

注記

支持脚（3箇所）に大きな衝撃を与えると、支持脚が破損するリスクがあります。

支持脚を傷付けないように、十分に注意して静かに置いてください。

実施する作業手順、または実施する作業手順の概要を示します。

補足情報を示します。

安全情報を示します。

4

No. 99MBF600B

■ かっこ、数字（□、1）の表記

本書で使用しているかっこ、および数字表記の意味を示します。

() (丸かっこ)	直前の内容の説明、補足説明を示します。
「」(かぎかっこ)	強調する語句を示します。また、参照文で参照先を示します。
□、□、□… 1、2、3…	作業の順番と、その内容を示します。 (□：親手順、1：子手順)

目次

本書で使用されているマークや文字	i
安全上のご注意	ii
取り扱い上のご注意	iii
輸出および非居住者への技術提供にあたってのご注意	iv
EU（欧州）諸国への輸出に関するご注意	iv
日本国内で本商品を廃棄する際のご注意	iv
保証	v
免責	v
本書について	vi
目次	viii
1 概要	1
1.1 特長.....	1
1.2 各部の名称と機能.....	2
2 セットアップ	3
2.1 梱包仕様.....	3
2.2 スコヤマスタの設置.....	4
2.3 輸送用固定具の取り外し・取り付け.....	5
2.4 検出器の取り付け.....	6
3 操作方法	9
3.1 校正・調整.....	9
3.2 測定.....	16
4 保守	19
5 仕様	21
5.1 仕様.....	21
5.2 標準付属品.....	21
5.3 オプション.....	22
5.3.1 ライザブロック（オプション）の設置	24
営業・サービスの窓口	App-1


1 概要

1.1 特長

本商品は、スライダーに取り付けた検出器（テストインジケータまたはレバーヘッドプローブ（オプション））を使用して、測定面の直角度や真直度を連続して測定する比較測定器です。

検出器の測定子を測定面に当て、スライダーを上下に摺動させることで得られるその変位から直角度を読み取ります。読み取った変位値から、各面の真直度や平行度を算出いただくこともできます。


測定の際は、別途用意いただいた直角定規（スコヤ）をマスタ（直角度基準）にして、本商品の直角度を校正・調整してから使用してください。より高精度に直角度や真直度を測定できます。



Tips

直角定規はお客様にて別途用意してください。

1.2 各部の名称と機能




No.	名称	機能
①	直角度調整ねじ	直角度の校正・調整時に使用します。
②	主柱	本商品の精度基準であるガイドです。
③	インジケータホルダ	スライダーに検出器を取り付けるためのホルダーです。 (長さ: 125 mm) (参照「2.4 検出器の取り付け」(6 ページ))
④	スライダー	主柱に沿って上下に摺動します。
⑤	目盛板	スライダーの位置や移動距離の目安として使用します。
⑥	フレーム	—
⑦	支持脚	フレームを支えます(超硬、3点支持)。
⑧	ストッパー球	直定規などの平行な治具を当てて、フレームを位置決めすることができます。
⑨	輸送用固定ねじ	輸送時、主柱が動かないように主柱を固定します。 (外側にキャップあり)
⑩	上下動ハンドル	スライダーを上下に移動します。

2 セットアップ

2.1 梱包仕様

本商品は、下図のように梱包されています。



No.	名称	個数	No.	名称	個数
(1)	コーナーパッド	16	(4)	段ボール (内側)	1
(2)	段ボール (中間)	1	(5)	緩衝材 (上側)	1
(3)	段ボール (外側)	1	(6)	緩衝材 (下側)	1

Tips

- 詳細は、別冊の「開梱・設置マニュアル」
- 標準付属品を確認してください。(「5.2 標準付属品」(21 ページ))

⚠ 注意

本商品は重量物のため (SL-450 の場合、24 kg)、落ちたり倒れたりすると、けがをするリスクがあります。



2人以上で開梱してください。

2.2 スコヤマスタの設置

次の手順で本商品を定盤の上に設置してください。

- 溶剤などを浸したレンズペーパーまたは繊維の出ない布などで、定盤面と本商品の支持脚（3箇所）の汚れや油を拭き取る

Tips

- ・ゴミ、汚れ、油などの付着は測定誤差の要因となります。
- ・推奨する溶剤：アルコール

- 本商品を定盤の上に設置する

注記

支持脚（3箇所）に大きな衝撃を与えると、支持脚が破損するリスクがあります。

- 支持脚を傷付けないように、十分に注意して静かに置いてください。

2.3 輸送用固定具の取り外し・取り付け

購入時、本商品のスライダー部は、輸送時の衝撃から保護するために固定されています。次の手順で輸送用固定具を取り外してください。

■ 取り外し

- 緩衝材 (①) を取り外す**
- 上ぶた固定ねじ (②、4本) を外し、上ぶた (③) を取り外す**
- バランサー固定ねじ (パーツ No. 390823) (④) を取り外す**

Tips

取り外したバランサー固定ねじ (④) は紛失しないように保管してください。バランサー固定ねじは、修理や大規模な移動のために本商品を輸送するときに必要です。

- !** 本商品を輸送する場合は、衝撃がかかるないように輸送用固定ねじ (図「1.2 各部の名称と機能」(2ページ)) を締め、バランサー固定ねじを取り付け、出荷時の箱で梱包してください。


- 上下動ハンドル (⑤) を動かし、スライダーが滑らかに動くことを確認する**

Tips

スライダーが滑らかに動かない場合は、お求めの販売店、または弊社営業・サービスの窓口へご連絡ください。

- 上ぶたを元に戻し、上ぶた固定ねじ (②、4本) で固定する**

- !** 上ぶた固定ねじ (②) は均等に締め付けてください。また、締め付けすぎないようにしてください。



■ 取り付け

「■ 取り外し」と逆の手順で輸送用固定具を取り付けてください。

2.4 検出器の取り付け


検出器は、測定用途に合わせてテストインジケータまたはオプションのレバーヘッドプローブ（電気マイクロメータ用検出器）を取り付けます。

ここでは、テストインジケータの取り付けについて説明します。

Tips

より高精度・高感度な測定を行う場合は、レバーヘッドプローブ（オプション）を使用してください。

検出器に応じてシステム用穴またはアリ溝を選択してください。




I インジケータホルダ (④) をスライダー (⑤) の取り付け溝に当てて、ねじ (③) で固定する


Tips

インジケータホルダ (④) の取り付け位置は、測定位置の高さに合わせて設定できます。測定ワークに合わせてねじ (③) の固定位置やインジケータホルダ (④) の向きを選び、位置を調整してください。

例 1 下向き



例 2 上向き



単位 : mm

■ クランプ (②) を使用して、検出器をインジケータホルダ (④) に取り付ける

Tips

検出器とクランプ (②) の固定方法は、システム用穴による固定 (①) とアリ溝による固定 (⑥) とを選択できます。検出器に合わせてお選びください。

詳細は、別冊の「テストインジケータ ユーザーズマニュアル」、別冊「ミューチェック用 レバー・ヘッド・プローブ ユーザーズマニュアル」

MEMO

3 操作方法

測定を行う前に、校正・調整を行います。

校正・調整は、テストインジケータまたはオプションのレバーヘッドプローブ（電気マイクロメータ用検出器）を取り付けた状態で、直角定規を測定し、本商品を操作した際に直角定規と同精度になるように調整します。


3.1 校正・調整

本商品のスライダー上下の動きに対して、前後方向および左右両方向の直角度を校正・調整します。より高精度・高感度な校正・調整を行う場合は、検出器にレバーヘッドプローブ（オプション）を使用してください。

- 前後方向および左右方向の直角度の校正・調整は、互いに影響し合う場合があります。必ず両方向の直角度を校正・調整してください。
- 本商品を輸送したとき、または本商品が衝撃を受けたときは、必ず再度の校正・調整を行ってください。
- 本商品の校正・調整を行ってから、ライザブロック（オプション）を設置してください。詳細は、「5.3.1 ライザブロック（オプション）の設置」(24ページ)


Tips

本調整は測定のたびに行う必要はありません。定期的に校正を行い、必要に応じて調整を行ってください。



■ 上ぶたの取り外し

□ 上ぶた固定ねじ（①、4本）を外し、上ぶた（②）を取り外す



■ 前後方向の校正・調整




締め付けたねじは、しばらくするとさらに締まり、直角度に影響する場合があります。そのため、締め付け後しばらくしてから直角度を再確認することをお勧めします。

□ 直角定規（③）の測定面が本商品と平行になるように、直角定規をセットする


Tips

本商品前面にある2つのストッパー球（図中*部）に直定規などの平行な治具を当て、その治具に沿って直角定規をセットすると、直角定規の測定面を本商品に対して平行にセットできます。



□ 検出器の測定子が、角度誤差の発生しない角度にセットされていることを確認する

詳細は、別冊の「テストインジケータ ユーザーズマニュアル」、別冊「ミューチェック用レバーヘッドプローブ ユーザーズマニュアル」



3 操作方法


■ ねじを緩める

- 1 ④、⑦のねじを緩める
- 2 輸送用固定ねじ（⑥、⑧）のキャップを取り外し、ねじを緩める

Tips

- ・輸送用固定ねじ（⑥、⑧）を緩めることで、主柱の位置を調整できるようになります。十分に緩めてください。
- ・取り外した輸送用固定ねじ（⑥、⑧）のキャップは校正・調整後に再度取り付けるため、紛失しないようにしてください。

- 3 ⑤のねじをいったん緩め、固定する程度まで締め直し、約15°程度再度緩める方向に回す



■ 上下動ハンドルを操作して、スライダーを摺動範囲の下端に移動する

■ 検出器の目盛を「0」に合わせる

テストインジケータの場合：外枠を回し、指針を「0」に合わせます。

レバーへッドプローブと電気マイクロメータの場合：ゼロ点調整つまみを回して指針を「0」に合わせます。

Tips

- ・テストインジケータの操作方法の詳細は、別冊の「テストインジケータ ユーザーズマニュアル」
- ・レバーへッドプローブの操作方法の詳細は、別冊の「ミューチェック用 レバーへッドプローブ ユーザーズマニュアル」
- ・電気マイクロメータの操作方法の詳細は、別冊の「電気マイクロメータ アナログミューチェック ユーザーズマニュアル」

■ 上下動ハンドルを操作して、スライダーを摺動範囲の上端にゆっくりと移動する

3 操作方法


□ 検出器の指示値を読み取る

指示値が「0」の場合：何度かスライダーを上下させ、スライダー上端部で「0」を表示することを確認し、手順□に進みます。

指示値が「0」でない場合：手順□に進みます。

□ 検出器の指示値が「0」になるように、

マイナスドライバーで偏心軸Aを調整する
直角度調整ねじ（⑪）を回し、主柱の前後
方向の傾きを調整する



□ 手順□に戻り、操作を繰り返す

» 検出器の指示値が「0」になる


□ ねじを締める

- 1 ⑫のねじを締める
- 2 輸送用固定ねじ（⑩）を緩めたまま、
⑨のねじを締める

□ 前後方向の直角度を確認する

調整した値から変化した場合、手順□からの操作を繰り返して調整します。

調整した値どおりであれば、「■左右方向の校正・調整」へ進みます。



■ 左右方向の校正・調整




本調整により締め付けたねじは、しばらくするとさらに締まり、直角度に影響する場合があります。そのため、締め付け後しばらくしてから直角度を再確認することをお勧めします。

■ 直角定規 (⑬) の測定面が本商品と直角になるように、直角定規の位置を変更する


Tips

本商品前面にある2つのストッパー球（図中*部）に直定規などの平行な治具を当て、その治具に沿って直角定規をセットすると、直角定規の測定面を本商品に対して直角にセットできます。




■ 検出器の方向を変える

詳細は、別冊の「テストインジケータ ユーザーズマニュアル」、別冊「ミューチェック用レバー・ヘッド・プローブ ユーザーズマニュアル」



■ ⑭のねじをいったん緩め、固定する程度まで締め直し、約15°程度再度緩める方向に回す



■ スライダーを摺動範囲の下端に移動する

3 操作方法

□ 検出器の目盛を「0」に合わせる

テストインジケータの場合：外枠を回し、指針を「0」に合わせます。

レバーヘッドプローブと電気マイクロメータの場合：ゼロ点調整つまみを回して指針を「0」に合わせます。

Tips

- ・ テストインジケータの操作方法の詳細は、別冊の「テストインジケータ ユーザーズマニュアル」
- ・ レバーヘッドプローブの操作方法の詳細は、別冊「ミューチェッカ用 レバーヘッドプローブ ユーザーズマニュアル」
- ・ 電気マイクロメータの操作方法の詳細は、別冊「電気マイクロメータ アナログミューチェッカ ユーザーズマニュアル」


□ スライダーを摺動範囲の上端にゆっくりと移動する

□ 検出器の指示値を読み取る

指示値が「0」の場合：何度かスライダーを上下させ、スライダー上端部で「0」を表示することを確認し、手順□に進みます。

指示値が「0」でない場合：手順□に進みます。

□ 検出器の指示値が「0」になるように、マイナスドライバーで偏心軸Bを調整する直角度調整ねじ（⑯）を回し、主柱の左右方向の傾きを調整する




□ 手順□に戻り、操作を繰り返す

» 検出器の指示値が「0」になる

□ ねじを締める

- 1 ⑯のねじを締める
- 2 輸送用固定ねじ（⑲）を緩めたまま、⑮のねじを締める
- 3 輸送用固定ねじ（⑱、⑲）のキャップを取り付ける



□ 左右方向の直角度を確認する

調整した値から変化した場合、手順□からの操作を繰り返して調整します。

□ 最終確認として、前後方向の直角度を再度確認する

調整した値どおりであれば、直角度の校正・調整は終了です。

■ 上ぶたの取り付け

■ 上ぶた固定ねじ（4本）を締め、上ぶたを元通りに取り付ける



上ぶた固定ねじは均等に締め付けてください。また、締め付けすぎないようにしてください。

3.2 測定

上下動ハンドルを操作してスライダーをゆっくりと摺動させ、検出器の指示値を読み取ります。より高精度・高感度な測定を行う場合は、検出器にレバー・ヘッド・プローブ（オプション）を使用してください。

注記

上下動ハンドルの摺動は軽くクランプ機構がないため、操作時にスライダーが動きすぎて、検出器が定盤や測定ワークなどに衝突し破損するリスクがあります。



- 上下動ハンドルを動かすときは、ゆっくりと操作してください。一回の測定で上下動ハンドルを上下に動かすと、ヒステリシスの影響で正確な測定ができないことがあります。
- 本商品を設置する定盤面の精度は、直角度の測定精度に大きく影響します。定盤も十分に注意して管理してください。
- 本商品のフレームやスライダーなどに衝撃を与えてしまった場合は、測定開始前に必ず校正・調整を行ってください。詳細は、図「3.1 校正・調整」(9 ページ)


Tips

- JIS1級以上の定盤をご使用ください。表面に傷や凹凸があると所定の性能が発揮できない場合があります。
- 直角定規などの取り扱い・設置姿勢、注意事項についてはメーカーの取扱説明書や成績書などを参照してください。

■ 本商品と測定ワークをセットする

Tips


本商品前面にある2つのストッパー球（図中*部）に直定規などの平行な治具を当て、その治具に沿って測定ワークをセットすると、測定ワークの測定面を本商品に対して平行にセットすることができます。



3 操作方法

□ 検出器の測定子が、角度誤差の発生しない角度にセットされていることを確認する

詳細は、別冊の「テストインジケータ ユーザーズマニュアル」、「ミューチェッカ用レバー・ヘッドプローブ ユーザーズマニュアル」



□ 上下動ハンドルでスライダーをゆっくりと摺動させ、検出器の測定子を測定開始点に移動する


□ 検出器の目盛を「0」に合わせる

テストインジケータの場合：外枠を回し、指針を「0」に合わせます。

レバー・ヘッドプローブと電気マイクロメータの場合：ゼロ点調整つまみを回して指針を「0」に合わせます。


Tips

- テストインジケータの操作方法の詳細は、別冊の「テストインジケータ ユーザーズマニュアル」
- レバー・ヘッドプローブの操作方法の詳細は、「ミューチェッカ用 レバー・ヘッドプローブ ユーザーズマニュアル」
- 電気マイクロメータの操作方法の詳細は、「電気マイクロメータ アナログ ミューチェッカ ユーザーズマニュアル」



3 操作方法


- 上下動ハンドルでスライダーを測定範囲の始点から終点までゆっくりと摺動させ、測定する



- 検出器の指示値を読み取る

Tips

上下動ハンドルから手を放し、指針が安定してから指示値を読み取ってください。測定範囲内の途中地点での測定値を読み取る場合も同様です。



Tips

本商品は、真直度を保証しています。目盛板の値を見ながら一定間隔で手順□と□の操作を繰り返し、検出器の読み取り結果をグラフ化すると、測定面の真直度を求めることができます。

4 保守

本商品の日常の点検、収納・保管について説明します。

本商品の性能を十分に発揮させ、安全に長期間ご使用いただくために、次の項目に従って実施してください。

△ 注意

本商品は重量物のため (SL-450の場合、24 kg)、落ちたり倒れたりすると、けがをするリスクがあります。

 移動する際は、本商品をしっかりと両手で持ち、2人以上で慎重に作業してください。

■ 日常の点検

外観の汚れや傷などを確認してください。



支持脚(3箇所)に傷があると正確な測定結果を得ることができません。支持脚は必ず確認してください。

■ 清掃

ご使用後は、溶剤などを浸したレンズペーパーまたは纖維の出ない布などで、支持脚(3箇所)と主柱の汚れを拭き取り、液体防錆油を薄く塗布してください(防錆処理)。



洗剤、シンナーやベンジンなどの有機溶剤は使用しないでください。

Tips

推奨する溶剤：アルコール

■ 収納・保管

清掃後に、本商品全体にクリアカバーを掛けて収納および直立状態で保管してください。


注記

本商品を再度梱包して長期保管する場合は、直立状態にしてください。横にして長期保管した場合、主柱が変形したり、スライダーの摺動が悪くなったりするリスクがあります。



本商品を梱包するときは、右図のように商品を横にして、ご購入時の段ボールや緩衝材を使って梱包してください。(図「2.1 梱包仕様」(3ページ))

正しく梱包しないと、移動時の衝撃などで本商品の精度が損なわれる可能性があります。



MEMO


5 仕様

5.1 仕様


コード No.	311-215	311-225	311-245
符号	SL-150	SL-250	SL-450
ストローク (mm)	150	250	450
直角度公差 (μm)	3	6	9
真直度公差 (μm)	2	2.5	3.5
外観寸法 (W x D x H) (mm)	180 x 200 x 420	180 x 200 x 520	220 x 220 x 720
質量 (kg)	13.7	16.2	24
精度保証環境	温度 : 20 °C ± 1.0 °C、湿度 : 23 % ~ 70 % (結露なきこと)		

5.2 標準付属品


パート No.	品名
513-401-10H	テストインジケータ (mm・てこ式ダイヤルゲージ)
902053	クランプ (テストインジケータ用)
601471	インジケータホルダ (125 mm)
650121	固定ねじ (インジケータホルダ用)
601614-3	クリアカバー (SL-150 にのみ付属)
601614-2	クリアカバー (SL-250 にのみ付属)
601614-1	クリアカバー (SL-450 にのみ付属)
538616	六角レンチ (3 mm)
99MBF600B	ユーザーズマニュアル (本書)
99MBF601B	開梱・設置マニュアル
—	保証書



テストインジケータ



クランプ



インジケータホルダ


5.3 オプション

- ライザブロック (SL-150、SL-250 のみ使用可)


コード No.	515-113	515-114	515-115
高さ (mm)	150	300	600
寸法許容差 (μm)	± 0.6	± 1.0	± 2.0
寸法許容差幅 (μm)	0.6	0.8	1.0
質量 (kg)	5.7	9.8	26.8



515-113




515-114



515-115


- エクステンションホルダ (パート No. 900551)

インジケータホルダの代わりとして使用します。測定位置を高くすることができます。




単位 : mm

- 電気マイクロメータ (コード No. 519-551)



5 仕様


● レバー-ヘッドプローブ (コード No. 519-521)




● レバー型フィーラ (パート No. 900565)

検出器の測定子では届かない部分を測定できます。

セット例




単位 : mm




● インジケータ微動ホルダ (パート No. 900571)

検出器の傾きを調整でき、指示値が簡単に調整できます。

セット例



単位 : mm



5.3.1 ライザブロック（オプション）の設置

オプションのライザブロックを定盤と本商品の間に設置することで、本商品の測定位置を高くすることができます。次の手順で実施してください。

Tips

- ・本商品の校正・調整を行ってから設置します。
- ・ライザブロックはSL-450には使用できません。

⚠ 注意

ライザブロックは重量物のため（515-115の場合、約26.8kg）、落ちたり倒れたりすると、けがをするリスクがあります。



移動する際は、ライザブロックをしっかりと両手で持ち、慎重に作業してください。

■ 溶剤などを浸したレンズペーパーまたは繊維の出ない布などで、定盤面とライザブロックの支持脚（下面3箇所）の汚れや油を拭き取る

Tips

- ・ゴミ、汚れ、油などの付着は測定誤差の要因となります。
- ・推奨する溶剤：アルコール

■ ライザブロックを定盤の上に設置する

注記

支持脚（上下各3箇所）に大きな衝撃を与えると、支持脚が破損するリスクがあります。



支持脚を傷付けないように、十分に注意して静かに置いてください。

■ ライザブロックの上に本商品を移動する

■ ライザブロックの上に本商品を設置する

ライザブロック上面にある2本の突起を、本商品下面にある取り付け用の穴に入れて設置してください。

⚠ 注意


本商品は重量物のため（SL-250の場合、約16kg）、落ちたり倒れたりすると、けがをするリスクがあります。



移動する際は、本商品をしっかりと両手で持ち、慎重に作業してください。



ライザブロックと本商品との間に手を挟んでけがをしないように注意してください。



Tips

- 取り外しは、設置と逆の手順で行ってください。
- ご使用後は、溶剤などを浸したレンズペーパーまたは繊維の出ない布などで、本商品の支持脚（3箇所）とライザブロックの支持脚（上下6箇所）の汚れを拭き取り、液体防錆油を薄く塗布してください（防錆処理）。
詳細は、図「4 保守」（19 ページ）
- 推奨する溶剤：アルコール

営業・サービスの窓口

2022年1月現在

仙台営業所	仙台市若林区卸町東 1-7-30 電話：(022) 231-6881	〒 984-0002 ファクス：(022) 231-6884
郡山営業所	仙台市若林区卸町東 1-7-30 (※) 電話：(024) 931-4331	〒 984-0002 ファクス：(022) 231-6884
宇都宮営業所	宇都宮市平松本町 796-1 電話：(028) 660-6240	〒 321-0932 ファクス：(028) 660-6248
水戸営業所	茨城県水戸市元吉田町 260-3 電話：(029) 303-5371	〒 310-0836 ファクス：(029) 303-5372
新潟営業所	新潟市中央区新和 1-6-10 リファーレ新和 1 階 B 号室 電話：(025) 281-4360	〒 950-0972 ファクス：(025) 281-4367
伊勢崎営業所	伊勢崎市宮子町 3463-13 電話：(0270) 21-5471	〒 372-0801 ファクス：(0270) 21-5613
さいたま営業所	さいたま市北区宮原町 3-429-1 電話：(048) 667-1431	〒 331-0812 ファクス：(048) 667-1434
川崎営業所	川崎市高津区坂戸 1-20-1 電話：(044) 813-1611	〒 213-8533 ファクス：(044) 813-1610
東京営業所	川崎市高津区坂戸 1-20-1 (※) 電話：(03) 3452-0481	〒 213-8533 ファクス：(044) 813-1610
厚木営業所	厚木市岡田 1-7-1 ヴェルドミール SUZUKI 105 号室 電話：(046) 226-1020	〒 243-0021 ファクス：(046) 229-5450
八王子駐在所	電話：(042) 620-5380	
富士駐在所	電話：(0545) 55-1677	
諏訪営業所	諏訪市中洲 582-2 電話：(0266) 53-6414	〒 392-0015 ファクス：(0266) 58-1830
上田駐在所	電話：(0268) 26-4531	
浜松営業所	浜松市東区和田町 587-1 電話：(053) 464-1451	〒 435-0016 ファクス：(053) 464-1683
安城営業所	安城市住吉町 5-19-5 電話：(0566) 98-7070	〒 446-0072 ファクス：(0566) 98-6761
中部オートモーティブ営業所	安城市住吉町 5-19-5 電話：(0566) 98-7070	〒 446-0072 ファクス：(0566) 98-6761
名古屋営業所	名古屋市昭和区鶴舞 4-14-26 電話：(052) 741-0382	〒 466-0064 ファクス：(052) 733-0921
金沢営業所	金沢市桜田町 1-26 ドマーニ桜田 電話：(076) 222-1160	〒 920-0057 ファクス：(076) 222-1161

※営業所の業務につきましては記載の住所にて行っております。

大阪営業所	大阪市住之江区南港北 1-4-34	〒 559-0034
	電話 : (06) 6613-8801	ファクス : (06) 6613-8817
神戸営業所	大阪市住之江区南港北 1-4-34 (※)	〒 559-0034
	電話 : (078) 924-4560	ファクス : (06) 6613-8817
京滋営業所	草津市大路 2-13-27 迂第 3 ビル 1F	〒 525-0032
	電話 : (077) 569-4171	ファクス : (077) 569-4172
岡山営業所	岡山市北区田中 134-107	〒 700-0951
	電話 : (086) 242-5625	ファクス : (086) 242-5653
広島営業所	東広島市八本松東 2-15-20	〒 739-0142
	電話 : (082) 427-1161	ファクス : (082) 427-1163
福岡営業所	福岡市博多区博多駅南 4-16-37	〒 812-0016
	電話 : (092) 411-2911	ファクス : (092) 473-1470
センシング営業課	川崎市高津区坂戸 1-20-1	〒 213-8533
	電話 : (044) 813-8236	ファクス : (044) 822-8140
地震機器課	川崎市高津区坂戸 1-20-1	〒 213-8533
	電話 : (044) 455-5021	ファクス : (044) 455-5019

※営業所の業務につきましては記載の住所にて行っております。

◆商品の故障および操作方法についてのご相談・お問い合わせ

カスタマーサポートセンタ 電話 : (0570) 073214 ファクス : (044) 813-1691

•受付時間：弊社営業日 8:30～12:00 13:00～17:15

•お願い： 测定機器商品（形状測定機、硬さ試験機、座標計測機器、画像測定機、光学機器ほか）に関するお問い合わせの場合は、該当商品のコード番号、シリアル番号をお手元にご用意ください。

改訂履歴

発行年月日	版数	改訂内容
2022年2月1日	初版	発行

株式会社 ミツトヨ

神奈川県川崎市高津区坂戸 1-20-1 〒 213-8533

ホームページ : <https://www.mitutoyo.co.jp>

Mitutoyo

Squareness Measuring Instrument Square Master

SL-150

SL-250

SL-450

User's Manual - Instructions for use -

Read this document thoroughly before operating the product.

After reading, retain it close at hand for future reference.

This English language version of the document contains
the original instructions.

No. 99MBF600B

Date of publication: February 1, 2022 (1)



■ Product names and model numbers covered in this document

Product name	Model number
Squareness measuring instrument Square Master	SL-150
	SL-250
	SL-450

■ Notice regarding this document

- Mitutoyo Corporation assumes no responsibilities for any damage to the product, caused by its use not conforming to the procedure described in this document.
- Upon loan or transfer of this product, be sure to attach this document to the product.
- In the event of loss or damage to this document, immediately contact a Mitutoyo sales office or your dealer.
- Before operation of the product, thoroughly read this document. Particularly, for full understanding of information, carefully read "Safety Precautions" and "Precautions for Use" at the outset of this document before using the product.
- The contents in this document are based on the information current as of February, 2022.
- No part or whole of this document may be transmitted or reproduced by any means without prior written permission of Mitutoyo Corporation.
- Some screen displays in this document may be highlighted, simplified or partially omitted for convenience of explanation. In addition, some of them may differ from actual ones to the extent that no user will misunderstand the functions and operations.
- The corporation, organization and product names that appear in this document are their trademarks or registered trademarks.

©2022 Mitutoyo Corporation. All rights reserved.

Conventions and Wording Used in This Document

■ Safety reminder conventions and wording warning against potential hazards

!CAUTION

Indicates a hazard with a low level of risk which, if not avoided, **could result in minor or moderate injury**.

NOTICE

Indicates a potentially hazardous situation which, if not avoided, **may result in property damage**.



Precaution to avoid pinched hands and arms

Alerts the user to a specific hazardous situation that may result in pinching.

■ Conventions indicating prohibited and mandatory actions



Indicates concrete information about prohibited actions.



Indicates concrete information about mandatory actions.

■ Conventions and wording indicating referential information or referential locations

Tips

Indicates further information and details relevant for the operating methods and procedures that are explained in that section.



Indicates referential locations if there is information that should be referred to in this document or an extraneous User's Manual.

E.g.: For details about XX, see "1.1 Names of Each Part" (page 5) in "1 Overview".

Safety Precautions

Read these "Safety Precautions" thoroughly before operating the product to use it properly.

These safety precautions include such information as to prevent an injury to the operator and other persons or damage to property. Be sure to observe the precautions.

CAUTION

Incorrectly handling this product or its optional accessories during relocation may cause injury.



This product is heavy (SL-450 weighs 24 kg). Do not allow it to be lifted or relocated by one person. Safety shoes are recommended for transportation and installation.



If this product falls down or falls over, it may cause injury. Handle it carefully.



When installing the product on a surface plate or the riser block (optional accessory), be careful to prevent your hands from being pinched and injured.

Precautions for Use

■ Product applications and handling

- This product is a squareness measuring instrument.

Do not use this product for any purposes other than measuring perpendicularity.

- This product is precision equipment.

It must be carefully handled. Be careful not to apply excessive shocks or force to any of the parts during unpacking, installation, use, or storage.

- If excessive shocks or force are applied to the product, the accuracy may be impaired.
- This product is only to be used in a standing position. Do not use it in a horizontal position.

■ Operating environment

Only use this product in the following environments.

- On a surface plate (required)
This product is designed to be installed on a precision surface plate. Prepare a precision surface plate.
- Areas subject to minimal dirt and dust
- Areas subject to minimal vibration
- Areas with the recommended temperature of about 20 °C and minimal temperature variation
- Areas with low humidity (70% or less)

Tips

Let the product sufficiently adjust to the temperature before use.

Avoid use in the following environments.

- Areas subject to direct cutting oil or water exposure
- Areas subject to direct sunlight, hot wind, or cold wind
- Areas directly in the path of an air conditioner

■ Transportation and relocation

When transporting the product, avoid excessive shocks by tightening the clamp screws for transportation (参照 "1.2 Part Names and Functions" (page 2)), mounting the balancer clamp screw (part No. 390823) (参照 "2.3 Installing and Removing the Securing Jigs for Transportation" (page 5)), and packing the product in the box that it was delivered in (参照 "2.1 Packing Specifications" (page 3)).

■ Disassembly and modification

This product was precisely adjusted during assembly. Do not make adjustments to the product that are not described in this document and do not disassemble or modify the product because the accuracy will be affected.

■ Maintenance

After use, remove dirt from the support legs (three places) and the column by using lens paper or a lint-free cloth, and then lightly apply a liquid rust-prevention oil (rust-prevention treatment). Do not use detergents or organic solvents such as thinner or benzine.

For details, see  "4 Maintenance" (page 19).

Export Control Compliance

This product falls into the Catch-All-Controlled Goods and/or Catch-All-Controlled Technologies (including Programs) under Category 16 of Appended Table 1 of Export Trade Control Order or under Category 16 of Appended Table of Foreign Exchange Control Order, based on Foreign Exchange and Foreign Trade Act of Japan.

If you intend re-export of the product from a country other than Japan, re-sale of the product in a country other than Japan, or re-providing of the technology (including Programs), you shall observe the regulations of your country.

Also, if an option is added or modified to add a function to this product, this product may fall under the category of List-Control Goods, List-Control Technology (including Programs) under Category 1 - 15 of Appended Table 1 of Export Trade Control Order or under Category 1 - 15 of Appended Table of Foreign Exchange Control Order, based on Foreign Exchange and Foreign Trade Act of Japan. In that case, if you intend re-export of the product from a country other than Japan, re-sale of the product in a country other than Japan, or re-providing of the technology (including Programs), you shall observe the regulations of your country. Please contact Mitutoyo in advance.

Notes on Export to EU Member Countries

When you intend exporting of this product to any of the EU member countries, it may be required to provide User's Manual(s) in English and EU Declaration of Conformity in English (under certain circumstances, User's Manual(s) in the destination country's official language and EU Declaration of Conformity in the destination country's official language). For detailed information, please contact Mitutoyo in advance.

Disposal of Products outside the European Union and Other European Countries

Please follow the official instruction in each community and country.

Warranty

This product has been manufactured under strict quality management, but should it develop problems within one year of the date of purchase in normal use, repair shall be performed free of charge. Please contact the agent where you purchased the product or Mitutoyo sales representative.

If this product fails or is damaged for any of the following reasons, it will be subject to a repair charge, even if it is still under warranty.

- Failure or damage owing to fair wear and tear
- Failure or damage owing to inappropriate handling, maintenance or repair, or to unauthorized modification
- Failure or damage owing to transport, dropping, or relocation of the product after purchase
- Failure or damage owing to fire, salt, gas, abnormal voltage, lightning surge, or natural disaster
- Failure or damage owing to use in combination with hardware or software other than those designated or permitted by Mitutoyo
- Failure or damage owing to use in ultra-hazardous activities

This warranty is effective only where the product is properly installed and operated in conformance with the instructions in this document within the original country of the installation.

EXCEPT AS SPECIFIED IN THIS WARRANTY, ALL EXPRESS OR IMPLIED CONDITIONS, REPRESENTATIONS, AND WARRANTIES OF ANY NATURE WHATSOEVER INCLUDING, WITHOUT LIMITATION, ANY IMPLIED WARRANTY OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, NONINFRINGEMENT OR WARRANTY ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE, ARE HEREBY EXCLUDED TO THE MAXIMUM EXTENT ALLOWED BY APPLICABLE LAW.

You assume all responsibility for all results arising out of its selection of this product to achieve its intended results.

Disclaimer

IN NO EVENT WILL MITUTOYO, ITS AFFILIATED AND RELATED COMPANIES AND SUPPLIERS BE LIABLE FOR ANY LOST REVENUE, PROFIT, OR DATA, OR FOR SPECIAL, DIRECT, INDIRECT, CONSEQUENTIAL, INCIDENTAL, OR PUNITIVE DAMAGES HOWEVER CAUSED AND REGARDLESS OF THE THEORY OF LIABILITY ARISING OUT OF THE USE OF OR INABILITY TO USE THIS PRODUCT EVEN IF MITUTOYO OR ITS AFFILIATED AND RELATED COMPANIES AND/OR SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

If, notwithstanding the foregoing, Mitutoyo is found to be liable to you for any damage or loss which arises out of or is in any way connected with use of this product by you, in no event shall Mitutoyo's and/or its affiliated and related companies' and suppliers' liability to you, whether in contract, tort (including negligence), or otherwise, exceed the price paid by you for the product only.

The foregoing limitations shall apply even if the above-stated warranty fails of its essential purpose. BECAUSE SOME COUNTRIES, STATES OR JURISDICTIONS DO NOT ALLOW THE EXCLUSION OR THE LIMITATION OF LIABILITY FOR CONSEQUENTIAL OR INCIDENTAL DAMAGES, IN SUCH COUNTRIES, STATES OR JURISDICTIONS, MITUTOYO'S LIABILITY SHALL BE LIMITED TO THE EXTENT PERMITTED BY LAW.

About This Document

■ Positioning of this document in document map

In addition to this document, a User's Manual related to the detector is available.

Square Master
User's Manual
(this document)

Unpacking and
Installation Manual

- Related to the detector (standard accessory)

Dial Test Indicator
User's Manual

- Related to the detector (optional accessory)

Electric Micrometer
Analog Mu-Checker
User's Manual

Lever Head Probe for
Mu-Checker
User's Manual

■ Intended readers and purpose of this document

- Intended readers

Persons with basic knowledge of calibrating measuring instruments.

They are assumed to be able to understand instructions by reading technical drawings.

- Purpose

The purpose of this document is to help you understand the overview of the Square Master, the functions of each part, how to use this product, and maintenance.

■ How to read this document

2 Setup	
2.2 Installing the Square Master	
 Install this product on a surface plate according to the following procedure	Indicates an operating procedure to be performed or its outline.
 Use lens paper or a lint-free cloth dipped in solvent, etc., to wipe dirt and oil off of the surface plate and the support legs (three places) of this product.	Indicates supplementary information.
 Tips <ul style="list-style-type: none">• The adhesion of dust, dirt, and oil is a cause of measurement error• Recommended solvent acetone	
 Install this product on the surface plate.	Indicates safety information.
 NOTICE The support legs (three places) may break if excessive force is applied.	
 Quietly and carefully place the product to prevent damage to the support legs.	

■ Brackets, quotation marks and numbers (, 1)

The meanings of brackets, quotation marks and numbers to be used in this document are as follows.

(): Round brackets	Represent a paraphrase of an immediately preceding phrase or a supplementary explanation.
" ": Double quotation marks	Represent a highlighted phrase. They also indicate an index where information to be referenced is described.
 1, 2, 3...	Indicates the order and the contents of tasks. ( : indicates main tasks, 1: indicates detailed tasks)

Contents

Conventions and Wording Used in This Document	i
Safety Precautions	ii
Precautions for Use.....	iii
Export Control Compliance	iv
Notes on Export to EU Member Countries	iv
Disposal of Products outside the European Union and Other European Countries ...	iv
Warranty	v
Disclaimer	v
About This Document.....	vi
Contents	viii
1 Overview.....	1
1.1 Characteristics	1
1.2 Part Names and Functions	2
2 Setup	3
2.1 Packing Specifications.....	3
2.2 Installing the Square Master	4
2.3 Installing and Removing the Securing Jigs for Transportation	5
2.4 Installing the Detector	7
3 How to Use.....	9
3.1 Calibration and Adjustment.....	9
3.2 Measurement	16
4 Maintenance	19
5 Specifications	21
5.1 Specifications	21
5.2 Standard Accessories	21
5.3 Optional Accessories	22
5.3.1 Installing the Riser Block (Optional Accessory)	24
SERVICE NETWORK	App-1


1 Overview

1.1 Characteristics

This product is a comparative measuring instrument that uses the detector (dial test indicator or lever head probe (optional accessory)) mounted on the slider to continuously measure the perpendicularity or straightness of the measuring surface.

Perpendicularity is read from the displacement obtained by touching the contact point of the detector against the measuring surface and sliding the slider up and down. Straightness and parallelism can be calculated from the displacement value that was read.


Before measuring, first set the separately prepared master square (square) as the master (perpendicularity standard), and calibrate and adjust the perpendicularity of the product. This allows perpendicularity and straightness measurements to be performed with greater accuracy.



Tips

The master square must be prepared separately.

1.2 Part Names and Functions




No.	Name	Function
①	Perpendicularity adjusting screw	Used when calibrating and adjusting perpendicularity.
②	Column	Guide that is the accuracy standard for the product.
③	Indicator holder	Holder for mounting the detector on the slider. (Length: 125 mm) (参见 "2.4 Installing the Detector" (page 7))
④	Slider	Slides up and down along the column.
⑤	Graduation plate	Used as an estimate of the position and movement distance of the slider.
⑥	Frame	—
⑦	Support legs	Supports the frame (carbide, 3-point support).
⑧	Stopper spheres	Positioning of the frame can be performed by using a parallel jig such as a straight edge.
⑨	Clamp screws for transportation	Secures the column to prevent it from moving during transportation. (with external caps)
⑩	Slider lever	Moves the slider up and down.

2 Setup

2.1 Packing Specifications

This product is packed as shown below.



No.	Name	Quantity	No.	Name	Quantity
(1)	Corner pad	16	(4)	Box (inner)	1
(2)	Box (middle)	1	(5)	Cushion pad (upper)	1
(3)	Box (outer)	1	(6)	Cushion pad (lower)	1

Tips

- For details, see the separate "Unpacking and Installation Manual".
- Check the standard accessories. ("5.2 Standard Accessories" (page 21))

⚠ CAUTION

This product is heavy (SL-450 weighs 24 kg). If it falls down or falls over, it may cause injury.



At least two people should unpack the product.

2.2 Installing the Square Master

Install this product on a surface plate according to the following procedure.

- I** Use lens paper or a lint-free cloth dipped in solvent, etc., to wipe dirt and oil off of the surface plate and the support legs (three places) of this product.

Tips

- The adhesion of dust, dirt, and oil is a cause of measurement error.
- Recommended solvent: alcohol

- I** Install this product on the surface plate.

NOTICE

The support legs (three places) may break if excessive force is applied.



Quietly and carefully place the product to prevent damage to the support legs.

2.3 Installing and Removing the Securing Jigs for Transportation

At the time of purchase, the slider part of this product is secured to protect it from shocks during shipping. Remove the securing jigs for transportation according to the following procedure.

■ Removal

- Remove the cushion pads (①).**
- Remove the upper cover screws (②, 4 pcs) and the upper cover (③).**
- Remove the balancer clamp screw (part No. 390823) (④).**

Tips

Store the removed balancer clamp screw (④) so that it does not get lost. This screw is necessary when transporting the product for repair or for major relocations.

- !** When transporting the product, avoid excessive shocks by tightening the clamp screws for transportation (参见 "1.2 Part Names and Functions" (page 2)), mounting the balancer clamp screw, and packing the product in the box that it was delivered in.


- Move the slider lever (⑤) to confirm that the slider moves smoothly.**

Tips

If the slider does not smoothly move, please contact the agent where you purchased the product or Mitutoyo sales representative.

- Restore the upper lid, and secure it with the upper cover screws (②, 4 pcs).**

- !** Evenly tighten the upper cover screws (②). Do not tighten them excessively.



■ Installation

Install the securing jigs for transportation by following "■ Removal" in the opposite order.

2.4 Installing the Detector


For the detector, install the dial test indicator or the lever head probe (optional accessory) (detector for electric micrometers) according to the purpose of the measurements.

Installation of the dial test indicator will be explained.

Tips

To measure with greater accuracy and sensitivity, use the lever head probe (optional accessory).

Select the stem hole or the dovetail according to the detector.




- I Insert the indicator holder (④) into the mounting groove of the slider (⑤), and secure it with the screw (③).**


Tips

The installation position of the indicator holder (4) can be set according to the height of the measurement position. Select the screw (3) securing position and the orientation of the indicator holder (4) according to the workpiece and adjust the position.

Example 1 Facing down



Example 2 Facing up



Unit: mm

 **Use the clamp (②) to install the detector on the indicator holder (④).**

Tips

The detector can be secured to the clamp (②) either by using the stem hole (①) or by using the dovetail (⑥). Select according to the detector.

For details, see  the separate "Dial Test Indicator User's Manual" and  "Lever Head Probe for Mu-Checker User's Manual".

3 How to Use

Calibrate and adjust the product before measuring.

Calibrate by measuring the master square with the dial test indicator or the lever head probe (optional accessory) (detector for electric micrometers) installed and make adjustments so that the accuracy obtained with the master square can be achieved when the product is operated.


3.1 Calibration and Adjustment

Calibrate and adjust the perpendicularity in the front/back and left/right directions relative to the up and down movements of the slider. To calibrate and adjust with greater accuracy and sensitivity, use the lever head probe (optional accessory) as the detector.

- Calibration and adjustment of the perpendicularity in the front/back or the left/right will affect the other directions. The perpendicularity in both directions must be calibrated and adjusted.
- The product must be calibrated and adjusted again after being transported or experiencing a physical shock.
- Install the riser block (optional accessory) after calibrating and adjusting the product. For details, see  "5.3.1 Installing the Riser Block (Optional Accessory)" (page 24).


Tips

This adjustment is not necessary for every measurement. Periodically calibrate and adjust as needed.



Front/back direction

 "■ Calibrating and adjusting in the front/back direction"




Left/right direction

 "■ Calibrating and adjusting in the left/right direction"

■ Removing the upper cover

- I** Remove the upper cover screws (①, 4 pcs) and the upper cover (②).



■ Calibrating and adjusting in the front/back direction




Already tightened screws may become tighter after a period of time, and this can affect perpendicularity. It is recommended to check the perpendicularity again awhile after the screws have been tightened.

- I** Set the master square (③) so that its measuring surface is parallel to the product.


Tips

Put a parallel jig such as a straight edge against the two stopper spheres (indicated by * in the figure) on the front side of the product. When the master square is set parallel to the jig, the measuring surface of the master square can be set parallel to the product.



- I** Confirm that the contact point of the detector is set at an angle at which no angular error will occur.

For details, see the separate "Dial Test Indicator User's Manual" and "Lever Head Probe for Mu-Checker User's Manual".




□ Loosen the screws.

- 1 Loosen screws ④ and ⑦.
- 2 Remove the caps of the clamp screws for transportation (⑥, ⑧) and loosen the screws.

Tips

- By loosening the clamp screws for transportation (⑥, ⑧), the position of the column can be adjusted. Loosen them sufficiently.
- The caps of the removed clamp screws for transportation (⑥, ⑧) will be reinstalled after calibration and adjustment. Do not lose them.

- 3 Loosen screw ⑤, re-tighten it enough to secure it, and then turn it about 15° in the loosening direction.



□ Operate the slider lever and move the slider to the bottom edge of its movement range.

□ Align the pointer on the detector to the "0" graduation.

Dial test indicator: Turn the bezel and align the pointer to "0".

Lever head probe and electric micrometer: Turn the zero point adjustment knob and align the pointer to "0".

Tips

- For details about how to operate the dial test indicator, see the separate "Dial Test Indicator User's Manual".
- For details about how to operate the lever head probe, see "Lever Head Probe for Mu-Checker User's Manual".
- For details about how to operate the electric micrometer, see "Electric Micrometer Analog Mu-Checker User's Manual".

□ Operate the slider lever and slowly move the slider to the top edge of its movement range.


■ Read the indicated value of the detector.

If the indicated value is "0": Move the slider up and down repeatedly. Confirm that "0" is displayed at the top edge, and proceed to step ■.

If the indicated value is not "0": Proceed to step ■.

■ Use a screwdriver to turn the perpendicularity

adjusting screw (⑪) that adjusts eccentric shaft A to adjust the tilt of the column in the front/back direction so that the indicated value of the detector is "0".




■ Return to step ■ and repeat the operations.

» The indicated value will be "0".

■ Tighten the screws.

- 1 Tighten screw ⑫.
- 2 While the clamp screw for transportation (⑩) is loose, tighten screw ⑨.



■ Check the perpendicularity in the front/back direction.

If the value changes from the adjusted value, adjust it by repeating the operations from step ■.

If the value is as adjusted, proceed to "■ Calibrating and adjusting in the left/right direction".

■ Calibrating and adjusting in the left/right direction




Screws tightened during this adjustment may become tighter after a period of time, and this can affect perpendicularity. It is recommended to check the perpendicularity again awhile after the screws have been tightened.

■ Change the position of the master square (⑬) so that its measuring surface is perpendicular to the product.


Tips

Put a parallel jig such as a straight edge against the two stopper spheres (indicated by * in the figure) on the front side of the product. When the master square is set parallel to the jig, the measuring surface of the master square can be set perpendicularly to the product.




■ Change the direction of the detector.

For details, see the separate "Dial Test Indicator User's Manual" and "Lever Head Probe for Mu-Checker User's Manual".



■ Loosen screw ⑭, re-tighten it enough to secure it, and then turn it about 15° in the loosening direction.



■ Move the slider to the bottom edge of its movement range.

□ Align the pointer on the detector to the "0" graduation.

Dial test indicator: Turn the bezel and align the pointer to "0".

Lever head probe and electric micrometer: Turn the zero point adjustment knob and align the pointer to "0".

Tips

- For details about how to operate the dial test indicator, see the separate "Dial Test Indicator User's Manual".
- For details about how to operate the lever head probe, see "Lever Head Probe for Mu-Checker User's Manual".
- For details about how to operate the electric micrometer, see "Electric Micrometer Analog Mu-Checker User's Manual".


□ Slowly move the slider to the top edge of its movement range.

□ Read the indicated value of the detector.

If the indicated value is "0": Move the slider up and down repeatedly. Confirm that "0" is displayed at the top edge, and proceed to step □.

If the indicated value is not "0": Proceed to step □.

□ Use a screwdriver to turn the perpendicularity adjusting screw (⑯) that adjusts eccentric shaft B to adjust the tilt of the column in the left/right direction so that the indicated value of the detector is "0".




□ Return to step □ and repeat the operations.

» The indicated value will be "0".

□ Tighten the screws.

- 1 Tighten screw ⑯.
- 2 While the clamp screw for transportation (⑯) is loose, tighten screw ⑮.
- 3 Install the caps of the clamp screws for transportation (⑯, ⑯).



□ Check the perpendicularity in the left/right direction.

If the value changes from the adjusted value, adjust it by repeating the operations from step □.

□ Check the perpendicularity in the front/back direction again as a final check.

If the value is as adjusted, the calibration and adjustment of perpendicularity is complete.

■ Installing the upper cover

 **Tighten the upper cover screws (4 pcs) and restore the upper cover.**



Evenly tighten the upper cover screws. Do not tighten them excessively.

3.2 Measurement

Operate the slider lever to slowly move the slider, and read the indicated value of the detector. To measure with greater accuracy and sensitivity, use the lever head probe (optional accessory) as the detector.

NOTICE

The slider may easily move too far when the slider lever is operated because the slider lever has no clamping mechanism, which may cause the detector to collide with the surface plate or the workpiece and break.



- Slowly operate the slider lever. Due to hysteresis, an accurate measurement may not be possible when moving the slider lever up and down for a single measurement.
- The surface plate on which this product is installed will have a significant influence on the measuring accuracy for perpendicularity. The surface plate must also be carefully managed.
- If the frame or slider of the product experiences a physical shock, calibration and adjustment must be performed before measuring. For details, see "3.1 Calibration and Adjustment" (page 9).

Tips


- Use a surface plate that conforms to JIS1 or higher. If the surface has scratches or unevenness, the specified performance may not be achievable.
- For handling, installation direction, and precautions regarding the master square, etc., refer to the user's manual and reports from the manufacturer.



Set the product and the workpiece.


Tips

Put a parallel jig such as a straight edge against the two stopper spheres (indicated by * in the figure) on the front side of the product. When the workpiece is set parallel to the jig, the measuring surface of the workpiece can be set parallel to the product.



□ Confirm that the contact point of the detector is set at an angle at which no angular error will occur.

For details, see the separate "Dial Test Indicator User's Manual" and "Lever Head Probe for Mu-Checker User's Manual".



□ Slowly move the slider lever of the slider to move the contact point of the detector to the measurement start position.


□ Align the pointer on the detector to the "0" graduation.

Dial test indicator: Turn the bezel and align the pointer to "0".

Lever head probe and electric micrometer: Turn the zero point adjustment knob and align the pointer to "0".


Tips

- For details about how to operate the dial test indicator, see the separate "Dial Test Indicator User's Manual".
- For details about how to operate the lever head probe, see "Lever Head Probe for Mu-Checker User's Manual".
- For details about how to operate the electric micrometer, see "Electric Micrometer Analog Mu-Checker User's Manual".



3 How to Use


- Use the slider lever to move the slider from the start position to the end position within the measuring range to perform the measurement.**



- Read the indicated value of the detector.**

Tips

Remove your hand from the slider lever, and read the indicated value after the pointer has stabilized. The procedure is the same for reading a measurement value at a point in the middle of the measuring range.



Tips

This product guarantees straightness. While looking at the graduation plate, repeat steps □ and □ at regular intervals. By graphing the results read by the detector, the straightness of the measuring surface can be obtained.

4 Maintenance

This part explains the daily inspections and the storage of the product.

In order to sufficiently utilize the performance of this product and safely use it for a long period of time, perform the following items.

⚠ CAUTION

This product is heavy (SL-450 weighs 24 kg). If it falls down or falls over, it may cause injury.

- ! When moving the product, grab both sides firmly with your hands and move it carefully with two or more people.

■ Daily inspections

Check the exterior for dirt or scratches.

- ! Accurate measurement results cannot be obtained if the support legs (three places) are scratched.
Always check the support legs.

■ Cleaning

After use, remove dirt from the support legs (three places) and the column by using lens paper or a lint-free cloth dipped in a solvent, etc., and then lightly apply a liquid rust-prevention oil (rust-prevention treatment).



Do not use detergents or organic solvents such as thinner or benzine.

Tips

Recommended solvent: alcohol

■ Storage

After cleaning, cover the entire product with a dust cover and store it in a standing position.


NOTICE

When repacking the product to store it for a long period of time, store it in a standing position. Storing the product in a horizontal position for a long period of time may deform the column or impair the movement of the slider.



When packing the product, turn it horizontally as shown in the figure on the right, and use the boxes and cushion pads from the time of purchase. (See "2.1 Packing Specifications" (page 3))

If the product is not packaged correctly, physical shocks during transportation could impair the accuracy of the product.



MEMO


5 Specifications

5.1 Specifications


Code No.	311-215	311-225	311-245
Model number	SL-150	SL-250	SL-450
Vertical travel (mm)	150	250	450
Squareness (μm)	3	6	9
Straightness (μm)	2	2.5	3.5
Dimensions (W x D x H) (mm)	180 x 200 x 420	180 x 200 x 520	220 x 220 x 720
Mass (kg)	13.7	16.2	24
Accuracy-guaranteed environment	Temperature: 20 °C±1.0 °C, humidity: 23 % through 70 % (no condensation)		

5.2 Standard Accessories


Part No.	Part name
513-401-10H	Dial test indicator (mm, lever-type dial gauge)
902053	Clamp (for dial test indicator)
601471	Indicator holder (125 mm)
650121	Fixing screw (for indicator holder)
601614-3	Dust cover (only included with the SL-150)
601614-2	Dust cover (only included with the SL-250)
601614-1	Dust cover (only included with the SL-450)
538616	Hexagonal-head wrench (3 mm)
99MBF600B	User's Manual (this document)
99MBF601B	Unpacking and Installation Manual
—	Warranty card



Dial test indicator



Clamp



Indicator holder


5.3 Optional Accessories

- Riser block (only for use with the SL-150 and SL-250)


Code No.	515-113	515-114	515-115
Height (mm)	150	300	600
Accuracy (μm)	± 0.6	± 1.0	± 2.0
Variation in length (μm)	0.6	0.8	1.0
Mass (kg)	5.7	9.8	26.8



515-113




515-114




515-115

- Extension holder (part No. 900551)

Used as an alternative to the indicator holder. The measurement position can be raised.




- Analog Mu-checker (Code No. 519-551)



5 Specifications



- Lever head probe (Code No. 519-521)



- Feeler (part No. 900565)

Can measure parts that cannot be reached by the contact point of the detector.


Setup example




- Adjustable holder (part No. 900571)

Can adjust the tilt of the detector and easily adjust the indicated value.

Setup example



Unit: mm



5.3.1 Installing the Riser Block (Optional Accessory)

By installing the riser block (optional accessory) between the surface plate and the product, the measurement position can be raised. Use the following procedures.

Tips

- Install after calibrating and adjusting the product.
- The riser block cannot be used with SL-450.

⚠ CAUTION

The riser block is heavy (515-115 weighs about 26.8 kg). If it falls down or falls over, it may cause injury.



When moving the riser block, grab both sides firmly with your hands and move it carefully.

- Use lens paper or a lint-free cloth dipped in solvent, etc., to wipe dirt and oil off of the surface plate and the support legs (three places on the bottom) of the riser block.

Tips

- The adhesion of dust, dirt, and oil is a cause of measurement error.
- Recommended solvent: alcohol

- Install the riser block on the surface plate.

NOTICE

The support legs (three places on both top and bottom) may break if excessive force is applied.



Quietly and carefully place the product to prevent damage to the support legs.

- Move the product to the top of the riser block.

- Install the product on the top of the riser block.

Install by inserting the two prongs on the top surface of the riser block into the mounting holes on the bottom surface of the product.

⚠ CAUTION


This product is heavy (SL-250 weighs about 16 kg). If it falls down or falls over, it may cause injury.



When moving the product, grab both sides firmly with your hands and move it carefully.



Be careful to prevent your hands from being pinched and injured between the riser block and the product.



Tips

- Remove by following the installation procedures in the opposite order.
- After use, remove dirt from the support legs (three places) of the product and the support legs (six places at top and bottom) of the riser block by using lens paper or a lint-free cloth dipped in a solvent, etc., and then lightly apply a liquid rust-prevention oil (rust-prevention treatment).
For details, see "4 Maintenance" (page 19).
- Recommended solvent: alcohol

SERVICE NETWORK

*As of August 2021

Europe

Mitutoyo Europe GmbH

Borsigstrasse 8-10, 41469 Neuss, GERMANY
TEL: 49 (0)2137 102-0 FAX: 49 (0)2137 102-351

Mitutoyo CTL Germany GmbH

Von-Gunzert-Strasse 17, 78727 Oberndorf, GERMANY
TEL: 49 (0)7423 8776-0 FAX: 49 (0)7423 8776-99

KOMEG Industrielle Messtechnik GmbH

Zum Wasserwerk 3, 66333 Völklingen, GERMANY
TEL: 49 (0)6898 91110 FAX: 49 (0)6898 9111100

Germany

Mitutoyo Deutschland GmbH

Borsigstrasse 8-10, 41469 Neuss, GERMANY
TEL: 49 (0)2137 102-0 FAX: 49 (0)2137 86 85

M³ Solution Center Hamburg

Tempowerkiring 9-im HIT-Technologiepark 21079
Hamburg, GERMANY
TEL: 49 (0)40 791894-0 FAX: 49 (0)40 791894-50

M³ Solution Center Berlin

Ernst-Lau-Straße 6, 12489 Berlin, GERMANY
TEL: 49 (0)30 2611 267 FAX: 49 30 67988729

M³ Solution Center Eisenach

Neue Wiese 4, 99817 Eisenach, GERMANY
TEL: 49 (0)3691 88909-0 FAX: 49 (0)3691 88909-9

M³ Solution Center Ingolstadt

Marie-Curie-Strasse 1A, 85055 Ingolstadt, GERMANY
TEL: 49 (0)841 954920 FAX: 49 (0)841 9549250

M³ Solution Center Leonberg

Am Längenbühl 3, 71229 Leonberg, GERMANY
TEL: 49 (0)7152 6080-0 FAX: 49 (0)7152 608060

Mitutoyo-Messgeräte Leonberg GmbH

Heidenheimer Strasse 14, 71229 Leonberg, GERMANY
TEL: 49 (0)7152 9237-0 FAX: 49 (0)7152 9237-29

U.K.

Mitutoyo (UK) Ltd. HQ

Joule Road, West Point Business Park,
Andover, Hampshire SP10 3UX, UNITED KINGDOM
TEL: 44 (0)1264 353123 FAX: 44 (0)1264 354883

Coventry M³ Solution Centre

Unit6, Banner Park, Wickmans Drive, Coventry,
West Midlands CV4 9XA, UNITED KINGDOM
TEL: 44 (0)2476 426300

Halifax M³ Solution Centre

Lowfields Business Park, Navigation Close, Elland,
West Yorkshire HX5 9HB, UNITED KINGDOM
TEL: 44 (0)1422 375566

East Kilbride M³ Solution Centre

The Baird Building, Rankine Avenue, Scottish
Enterprise Technology Park, East Kilbride G75
0QF, UNITED KINGDOM
TEL: 44 (0)1355 581170

France

Mitutoyo France

Paris Nord 2-123 rue de la Belle Etoile, BP 59267
ROISSY EN FRANCE 95957 ROISSY CDG
CEDEX, FRANCE
TEL: 33 (0)149 38 35 00

M³ Solution Center LYON

Parc Mail 523, cours du 3ème millénaire, 69791
Saint-Priest, FRANCE
TEL: 33 (0)149 38 35 70

M³ Solution Center STRASBOURG

Parc de la porte Sud, Rue du pont du péage,
67118 Geispolsheim, FRANCE
TEL: 33 (0)149 38 35 80

M³ Solution Center CLUSES

Espace Scionzier 480 Avenue des Lacs, 74950
Scionzier, FRANCE
TEL: 33 (0)149 38 35 90

M³ Solution Center TOULOUSE

Aeroparc Saint Martin Cellule B08 ZAC de Saint
Martin du Touch 12 rue de Caulet 31300
Toulouse, FRANCE
TEL: 33 (0)149 38 42 90

M³ Solution Center RENNES

2, rue Claude Chappe, PA le Vallon - ZAC
Mivoie, 35230 Noyal-Châtillon-sur-Seiche,
FRANCE
TEL: 33 (0)149 38 42 10

Italy

Mitutoyo Italiana S.r.l.

CORSO EUROPA, 7 - 20045 LAINATE (MI), ITALY
TEL: 39 02 935781 FAX: 39 02 93578255

M³ Solution Center BOLOGNA

VIA DEI CARPINI 1/A - 40011 ANZOLA EMILIA (BO), ITALY
TEL: 39 02 93578215 FAX: 39 02 93578255

M³ Solution Center CHIETI

Contrada Santa Calcagna - 66020 Rocca S.
Giovanni (CH), ITALY
TEL: 39 02 93578280 FAX: 39 02 93578255

M³ Solution Center PADOVA

VIA G. GALILEI 21/F - 35035 MESTRINO (PD), ITALY
TEL: 39 02 93578268 FAX: 39 02 93578255

Netherlands

Mitutoyo Nederland B.V.

KONINGSSCHOT 41, 3905 PR VEENENDAAL,
THE NETHERLANDS
TEL: 31(0)318-534911

Mitutoyo Nederland B.V. / M³ Solution Center Enschede

INSTITUUTENWEG 50, 7521 PK ENSCHEDE,
THE NETHERLANDS
TEL: 31(0)318-534911

Mitutoyo Nederland B.V. / M³ Solution Center Eindhoven

DE RUN 1115, 5503 LB VELDHOVEN,
THE NETHERLANDS
TEL: 31(0)318-534911

Mitutoyo Research Center Europe B.V.

DE RIJN 18, 5684 PJ BEST, THE NETHERLANDS
TEL: 31(0)499-320200 FAX: 31(0)499-320299

Belgium

Mitutoyo Belgium N.V. / M³ Solution Center Melsele

SCHAARBEEKstraat 20, B-9120 MELSELE, BELGIUM
TEL: 32 (0)3-2540444

Sweden

Mitutoyo Scandinavia AB

SLÄNTVÄGEN 6, 194 27 UPPLANDS VÄSBY, SWEDEN
TEL: 46 (0)8 594 109 50 FAX: 46 (0)8 590 924 10

Mitutoyo Scandinavia AB / M³ Solution Cen- ter Alingsås

ÄNGSVAKTAREGATAN 3A, 441 38 ALINGSÅS, SWEDEN
TEL: 46 (0)8 594 109 50 FAX: 46 (0)322 63 31 62

Mitutoyo Scandinavia AB / M³ Solution Cen- ter Värnamo

KALKSTENSväGEN 7, 331 44 VÄRNAMO, SWEDEN
TEL: 46 (0)8 594 109 50 FAX: 46 (0)370 463 34

Switzerland

Mitutoyo (Schweiz) AG

STEINACKERSTRASSE 35, 8902 URDORF, SWITZERLAND
TEL: 41 (0)447361150

Mitutoyo (Suisse) SA

RUE GALILIÉ 4, 1400 YVERDON-LES BAINS, SWITZERLAND
TEL: 41 (0)244259422 FAX: 41 (0)447361151

Poland

Mitutoyo Polska Sp.z o.o.

UL.GRANICZNA 8A, 54-610 WROCŁAW, POLAND
TEL: 48 (0)71354 83 50 FAX: 48 (0)71354 83 55

Czech Republic

Mitutoyo Česko s.r.o.

DUBSKÁ 1626, 415 01 TEPlice, CZECH REPUBLIC
TEL: 420 417-514-011 Email: info@mitutoyo.cz

Mitutoyo Česko s.r.o. M³ Solution Center Ivančice

KE KARLOVU 62/10, 664 91 IVANČICE, CZECH REPUBLIC
TEL: 420 417-514-011 Email: info@mitutoyo.cz

Mitutoyo Česko s.r.o. M³ Solution Center Ostrava Mošnov

MOŠNOV 314, 742 51 MOŠNOV, CZECH REPUBLIC
TEL: 420 417-514-050 Email: info@mitutoyo.cz

Mitutoyo Česko s.r.o. Slovakia Branch

Hviezdoslavova 124, 017 01 Povážská
Bystrica, SLOVAKIA
TEL: 421 948-595-590 Email: info@mitutoyo.sk

Hungary

Mitutoyo Hungária Kft.

ZÁHONY UTCA 7, D-ÉPÜLET / FSZ, 1031 BUDAPEST, HUNGARY
TEL: 36 (0)1 2141447 FAX: 36 (0)1 2141448

Romania

Mitutoyo Romania SRL

1A DRUMUL GARII ODAI STREET, SHOWROOM, GROUND
FLOOR, 075100 OTOPENI-ILFOV, ROMANIA
TEL: 40 (0)311012088 FAX: +40 (0)311012089

Showroom in Brasov

STRADA IONESCU CRUM NR.1, BRASOV BUSINESS
PARK TURNUL 1, MEZANIN, 500446
BRASOV-JUDETUL BRASOV, ROMANIA
TEL/FAX: 40 (0)371020017

Russian Federation

Mitutoyo RUS LLC

Sharikopodshipnikovskaya St., 13, bld.5, Moscow, 115088, RUSSIAN FEDERATION

TEL: 7 495 545 43 90

Finland

Mitutoyo Scandinavia AB Finnish Branch

Viherkäitäjä 2A, 33960, Pirkkala, FINLAND

TEL: 358 (0)40 355 8498

Austria

Mitutoyo Austria GmbH

Salzburger Straße 260 / 3 A-4600 Wels, AUSTRIA

TEL: 43 (0)7242 219 998

Mitutoyo Austria GmbH Goetzis Regional showroom

Lastenstrasse 48a, 6840 Götzing, AUSTRIA

Singapore

Mitutoyo Asia Pacific Pte. Ltd.

Head office / M³ Solution Center

24 Kallang Avenue, Mitutoyo Building,
SINGAPORE 339415

TEL:(65)62942211 FAX:(65)62996666

Malaysia

Mitutoyo (Malaysia) Sdn. Bhd.

Kuala Lumpur Head Office / M³ Solution Center

Mah Sing Integrated Industrial Park, 4, Jalan Utarid U5/14,
Section U5, 40150 Shah Alam, Selangor, MALAYSIA

TEL:(60)3-78459318 FAX:(60)3-78459346

Penang Branch office / M³ Solution Center

30, Persiaran Mahsuri 1/2, Sunway Tunas, 11900
Bayan Lepas, Penang, MALAYSIA

TEL:(60)4-6411998 FAX:(60)4-6412998

Johor Branch office / M³ Solution Center

70 (Ground Floor), Jalan Molek 1/28, Taman
Molek, 81100 Johor Bahru, Johor, MALAYSIA
TEL:(60)7-3521626 FAX:(60)7-3521628

Thailand

Mitutoyo (Thailand) Co., Ltd.

Bangkok Head Office / M³ Solution Center

76/3-5, Chaengwattana Road, Kwaeng Anusaowaree,
Khet Bangkaen, Bangkok 10220, THAILAND

TEL:(66)2080 3500 FAX:(66)2521 6136

Chonburi Branch / M³ Solution Center

7/1, Moo 3, Tambon Bowin, Amphur Sriracha,
Chonburi 20230, THAILAND

TEL:(66)2080 3563 FAX:(66)3834 5788

ACC Branch / M³ Solution Center

122/8, 122/9, Moo 6, Tambon Donhuaroh, Amphur
Muangchonburi, Chonburi 20000, THAILAND

TEL:(66)2080 3565

Indonesia

PT. Mitutoyo Indonesia

Head Office / M³ Solution Center

Jalan Sriwijaya No.26 Desa cibatu Kec. Cikarang
Selatan Kab. Bekasi 17530, INDONESIA

TEL: (62)21-2962 8600 FAX: (62)21-2962 8604

Vietnam

Mitutoyo Vietnam Co., Ltd

Hanoi Head Office / M³ Solution Center

1st & 2nd floor, MHDI Building, No. 60 Hoang Quoc
Viet Road, Nghia Do Ward, Cau Giay District, Hanoi,
VIETNAM

TEL:(84)24-3768-8963 FAX:(84)24-3768-8960

Ho Chi Minh City Branch Office / M³ Solution Center

123 Dien Bien Phu Street,Ward 15,Binh Thanh
District, Ho Chi Minh City, VIETNAM

TEL:(84)28-3840-3489 FAX:(84)28-3840-3498

Hai Phong City Branch Office

Room 511, 5th Floor, Thanh Dat 3 Building, No. 4
Le Thanh Tong Street, May To Ward, Ngo Quyen
District, Hai Phong City, VIETNAM

TEL:(84)22-5398-9909

Philippines

Mitutoyo Philippines, Inc.

Head Office / M³ Solution Center

Unit 1B & 2B LTI, Administration Building 1, Annex 1, North
Main Avenue, Laguna Technopark, Binan Laguna 4024,
PHILIPPINES

TEL/FAX:(63) 49 544 0272

India

Mitutoyo South Asia Pvt. Ltd. Head Office

C-122, Okhla Industrial Area, Phase-I,
New Delhi-110 020, INDIA

TEL:(91) 11-26372090 FAX: (91) 11-26372636

MSA Technical Center

Plot no. 65, Ground Floor, Udyog Vihar, Phase-4 Gurgaon,
Haryana - 122016, INDIA

TEL : (91) 124-2340286/287

Mumbai Region Head office

303, Sentinel Hiranandani Business Park Powai,
Mumbai-400 076, INDIA

TEL:(91) 22-25700684/837/839 FAX: (91) 22-25700685

Pune Office / M³ Solution Center

G4/G5, Pride Kumar Senate, Off. Senapati Bapat Road, Pune-411 016, INDIA
TEL:(91) 20-25660043/44/45 FAX: (91) 20-66033644

Bengaluru Region Head office / M³ Solution Center

116/117-2, Ground Floor, Sy. No. 93 & 94, 3rd Phase, Peenya Industrial Area, Bengaluru-560 058, INDIA
TEL:(91) 80-25630946/47/48

Chennai Office / M³ Solution Center

No. 624, Anna Salai Teynampet, Chennai-600 018, INDIA
TEL: (91) 44-24328823/24
FAX: (91) 44-24328825

Kolkata Office

Unit No. 1208,Om Tower, 32,J.L..Nehru Road, Kolkata-700 071, INDIA
Tel: 91 33-22267088/40060635 Fax: (91) 33-22266817

Ahmedabad Office/M³ Solution Center (Ahmedabad)

A-104 & A-105, First Floor, Solitaire Corporate Park, Near Divya Bhaskar Press, S.G. Road, Ahmedabad - 380 015, INDIA
TEL: (91) 079 - 29704902/903

Coimbatore Office

Regus, Srivari Srimath, 3rd Floor, Door No:1045, Avinashi Road, Coimbatore - 641 018,INDIA
TEL: (91) 9345005663

Taiwan

Mitutoyo Taiwan Co., Ltd. / M³ Solution Center Taipei
4F., No.71, Zhouzi St., Neihu Dist.,Taipei City 114, TAIWAN (R.O.C.)
TEL:886(2)5573-5900 FAX:886(2)8752-3267

Taichung Branch / M³ Solution Center Taichung

1F., No. 299, Gaotie 1st Rd., Wuri Dist., Taichung City 414, TAIWAN (R.O.C.)
TEL:886(4)2338-6822 FAX:886(4)2338-6722

Kaohsiung Branch / M³ Solution Center Kaohsiung

1F., No.31-1, Haibian Rd., Lingya Dist., Kaohsiung City 802, TAIWAN (R.O.C.)
TEL:886(7)334-6168 FAX:886(7)334-6160

South Korea**Mitutoyo Korea Corporation****Head Office / M³ Solution Center**

(Sanbon-Dong, Geumjeong High View Build.), 6F, 153-8, Ls-Ro, Gunpo-Si, Gyeonggi-Do, 15808 KOREA
TEL:82(31)361-4200 FAX:82(31)361-4201

Busan Office / M³ Solution Center

(3150-3, Daejeo 2-dong) 8,Yutongdanji 1-ro 49beon-gil, Gangseo-gu, Busan, 46721 KOREA
TEL:82(51)324-0103 FAX:82(51)324-0104

Daegu Office / M³ Solution Center

(Galsan-dong, Daegu Business Center), 301-Ho, 217, Seongseogongdan-ro, Dalseo-gu, Daegu 42704 KOREA
TEL:82(53)593-5602 FAX:82(53)593-5603

China

Mitutoyo Measuring Instruments (Shanghai) Co., Ltd.
8th Floor, Tower 1 Lujiazui Jinkong Square No.1788/1800 Century Ave., Pudong New District, Shanghai 200122, CHINA
TEL:86(21)5836-0718 FAX:86(21)5836-0717

Suzhou Office / M³ Solution Center (Suzhou)
No. 46 Baiyu Road, Suzhou 215021, CHINA
TEL:86(512)6522-1790 FAX:86(512)6251-3420

Wuhan Office / M³ Solution Corner

Room 1701, Wuhan Wanda Center, No. 96, Linjiang Road, Wuchang District, Wuhan Hubei 430060, CHINA
TEL:86(27)8544-8631 FAX:86(27)8544-6227

Chengdu Office

1-701, New Angle Plaza, 668# Jindong Road, Jinjiang District, Chengdu, Sichuan 610066,CHINA
TEL:86(28)8671-8936 FAX:86(28)8671-9086

Hangzhou Office

Room 804, Eastern International Business Center Building 1, No.600 Jinsha Road of Hangzhou Economic and Technological Development Zone, 310018, CHINA
TEL: 86(571)8288-0319 FAX: 86(571)8288-0320

Tianjin Office / M³ Solution Center China (Tianjin)

Room D 12/F, TEDA Building, No.256 Jie-fang Nan Road Hexi District,Tianjin 300042, CHINA
TEL:86(22)5888-1700 FAX:86(22)5888-1701

Changchun Office

Room 815, 8F, Building A1, Upper East International No.3000 Dongsheng Street, Erdao District, Changchun, Jilin, 130031, CHINA
TEL:86(431)8192-6998 FAX:86(431)8192-6998

Chongqing Office

Room 1312, Building 3, Zhongyu Plaza, No.86, Hongjin Avenue,Longxi Street, Yubei District, Chongqing, 400000, CHINA
TEL:86(23)6595-9950 FAX:86(23)6595-9950

Qingdao Office

Room 638, 6F, No.192 Zhengyang Road, Chengyang District, Qingdao, Shandong, 266109, CHINA
TEL:86(532)8096-1936 FAX:86(532)8096-1937

Xi'an Office

Room 805, Xi'an International Trade Center, No. 196 Xiaozhai East Road, Xi'an, 710061, CHINA
TEL:86(29)8538-1380 FAX:86(29)8538-1381

Dalian Office / M³ Solution Center China (Dalian)

Room A-106 Shuijing SOHO, No.16 Harbin Road,Economic Development Zone,Dalian, 116600 CHINA
TEL:86(411)8718 1212 FAX:86(411)8754-7587

Zhengzhou Office

Room1801,18/F,Unit1,Building No.23, Shangwu Inner Ring Road, Zhengdong New District,Zhengzhou City, Henan 450018, CHINA
TEL:86(371)6097-6436 FAX:86(371)6097-6981

Dongguan Office / M³ Solution Center China (Dongguan)

Room 801, No 65, Chang'an Section Guanchang Road, Chang'an Town, Dongguan City, Guangdong 523841, CHINA
TEL:86(769)8541 7715 FAX:86(769)-8541 7745

Fuzhou Office

Room 2104, City Commercial Centre, No.129 Wu Yi Road N., Fuzhou City, Fujian 350005, CHINA
TEL 86 (591) 8761 8095
FAX 86 (591) 8761 8096

Changsha Office

Room 2207, Building 1, Shiner International Plaza, No. 88, Kaiyuan Middle Road, Changsha City, Hunan 410100, CHINA
TEL 86 (731) 8401 9276
FAX 86 (731) 8401 9376

Mitutoyo Measuring Instruments (Suzhou) Co., Ltd.

No. 46 Baiyu Road, Suzhou 215021, CHINA
TEL:86(512)6252-2660 FAX:86(512)6252-2580

U.S.A.**Mitutoyo America Corporation**

965 Corporate Blvd., Aurora, IL 60502, U.S.A.
TEL:1-(630)820-9666 Toll Free No. 1-888-648-8869
FAX:1-(630)978-3501

Headquarters (Aurora) / M³ Solution Center

965 Corporate Blvd., Aurora, IL 60502, U.S.A.

Seattle (Renton) Office / M³ Solution Center

1000 SW 34th St. Suite G, Renton,
WA 98057 U.S.A.
TEL:1-(888)-648-8869

Houston Office / M³ Solution Center

4560 Kendrick Plaza Drive Suite 120 Houston, TX 77032, U.S.A.
TEL:1-(888)-648-8869 FAX:1-(281)227-0937

Cincinnati (Mason) Office / M³ Solution Center

6220 Hi-Tek Ct., Mason, OH 45040, U.S.A.
TEL:1-(888)-648-8869 FAX:1-(513)754-0718

Detroit (Novi) Office / M³ Solution Center

46850 Magellan Drive, Suite 100 Novi, MI 48377, U.S.A.
TEL:1-(888)-648-8869 FAX: 1-(248)-926-0928

Los Angeles (City of Industry) Office / M³ Solution Center

16925 E. Gale Ave., City of Industry, CA 91745, U.S.A.
TEL:1-(888)-648-8869 FAX:1-(626)369-3352

Charlotte (Huntersville) Office / M³ Solution Center

11515 Vanstory Dr., Suite 140, Huntersville, NC 28078, U.S.A.
TEL:1-(888)-648-8869 FAX:1-(704)875-9273

Boston (Marlborough) Office / M³ Solution Center

753 Forest Street, Suite 110, Marlborough, MA 01752, U.S.A.
TEL:1-(888)648-8869 FAX:1-(508)485-0782

Mitutoyo America Corporation Calibration Lab

965 Corporate Blvd., Aurora, IL 60502, U.S.A.
TEL:1-(888)-648-8869 FAX:1-(630)978-6477

Mitutoyo Research & Development America, Inc.

11533 NE 118th St., Kirkland,
WA 98034-7111, U.S.A.
TEL:1-(425)821-3906 FAX:1-(425)821-3228

Mitutoyo Research & Development America, Inc. - California Office

16925 Gale Ave. City of Industry,
CA 91745-1806 U.S.A.
TEL: 1-(425)821-3906 FAX: 1-(425)821-3228

Mitutoyo America Corporation CT-Lab Chicago

965 Corporate Blvd., Aurora, IL 60502, U.S.A.
TEL: 1-(888)-648-8869 FAX: 1-(630)-820-3418

Canada

Mitutoyo Canada Inc.

2121 Meadowvale Blvd., Mississauga,
Ont. L5N 5N1., CANADA
TEL:1-(905)821-1261 FAX:1-(905)821-4968

Montreal Office

7075 Place Robert-Joncas Suite 129, Montreal,
Quebec H4M 2Z2, CANADA
TEL:1-(514)337-5994 FAX:1-(514)337-4498

Brazil

Mitutoyo Sul Americana Ltda.

Head office / M³ Solution Center
Rodovia Índio Tibiriçá 1555, CEP 08655-000 -
Vila Sol Nascente - Suzano - SP - BRASIL
TEL:55 (11)5643-0040

Argentina

Mitutoyo Sul Americana Ltda.

Argentina Branch / M³ Solution Center
Av. B. Mitre 891/899 – C.P. (B1603CQI)
Vicente López –Pcia. Buenos Aires – ARGENTINA
TEL:54(11)4730-1433 FAX:54(11)4730-1411

Sucursal Cordoba / M³ Solution Center

Av. Ricchieri 2872 L.4 – Bº Jardin – CP X5014O-
PJ Cordoba, ARGENTINA
TEL:54 (351) 464-4125

Mexico

Mitutoyo Mexicana, S.A. de C.V.

Industria Eléctrica No.15, Parque Industrial, Nau-
calpan de Juárez, Estado de México C.P.53370,
MÉXICO
TEL: 52 (01-55) 5312-5612
FAX: 52 (01-55) 5312-3380

Monterrey Office / M³ Solution Center

Bvl. Interamericana No. 103, Parque Industrial
FINSA, C.P. 66636 Apodaca, N.L., MÉXICO
TEL: 52(01-81) 8398-8227/8228/8242/8244
FAX: 52(01-81) 8398-8226

Tijuana Office / M³ Solution Center

Calle José María Velazco 10501-C, Col. Cd. Industrial
Nueva Tijuana, C.P. 22500 Tijuana, B.C., MÉXICO
TEL: 52 (01-664) 647-5024

Querétaro Office / M³ Solution Center

Av. Cerro Blanco No.500-1, Colonia Centro Sur,
Querétaro, Querétaro, C.P. 76090, MÉXICO
TEL: 52 (01-442) 340-8018, 340-8019 and 340-8020
FAX: 52 (01-442) 340-8017

Mitutoyo Mexicana, S.A. de C.V. Querétaro Calibration Laboratory

Av. Cerro Blanco 500 30 Centro Sur,
Querétaro, Querétaro, C.P. 76090, MÉXICO
TEL: 52 (01-442) 340-8018, 340-8019 and 340-8020
FAX: 52 (01-442) 340-8017

Aguascalientes Office / M³ Solution Center

Av. Aguascalientes No. 622, Local 15 Centro Comer-
cial El Cilindro Fracc. Pulgas Pandas Norte, C.P.
20138, Aguascalientes, Ags. MÉXICO

TEL: 52 (01-449) 174-4140 and 174-4143

Irapuato Office / M³ Solution Center

Boulevard a Villas de Irapuato No. 1460 L.1 Col. Ejido
Irapuato C.P. 36643
Irapuato, Gto., MÉXICO
TEL: 52 (01-462) 144-1200 and 144-1400

Revision Record

Date of publication	Revision status	Details of revision
February 1, 2022	First edition	Publication

Mitutoyo Corporation

20-1, Sakado 1-Chome, Takatsu-ku, Kawasaki-shi, Kanagawa 213-8533, Japan

Tel: +81 (0)44 813-8230 Fax: +81 (0)44 813-8231

Home page: <https://www.mitutoyo.co.jp/global.html>

For the EU Directive, Authorized representative and importer in the EU:

Mitutoyo Europe GmbH

Borsigstrasse 8-10, 41469 Neuss, Germany

Printed in Japan

No. 99MBF600B